

Gen-AIR-ator

GEN-AIR-ATOR PRICE LIST

Effective January 1, 2018

Part Number	Description	Price
1-33-RXP-1	GEN-AIR-ATOR - Complete w/ 400' of 1/2" Flex Airline	\$ 865.00
1-33-RXP-2	GEN-AIR-ATOR - Complete - Less Flex Airline	835.00
1-33-RXP-3	Power Unit - Only	725.00
RXP-201	Compressor Assembly	\$ 525.00
RXP-299	Venturi Air Diffuser w/ Install Kit	215.00
RXP-312	400' Roll of 1/2" Flex Airline	95.00

GEN-AIR-ATOR Parts (1-33-RXP)

Part Number	Description	Price
* K-33-RXP	Repair Kit - 1 1/4" Wide Vanes, Intake Filter (1-33-RXP)	\$ 90.00
630-013	Intake Air Filter Assembly	19.00
630-014	Intake Air Filter Elements (2)	12.00
753-001	Fan Blade w/ Stem	\$ 25.00
413-001	Check Valve Assembly	25.00
613-001	Air Gauge	25.00
263-001	1/4" Air Hose	6.25
653-004	1/2" Flex Pipe Coupling	5.50
413-009	Venturi Spike 1/2" x 13"	\$ 6.50
653-005	Venturi Cable Ties (40)	12.00
123-001	S.S. Hose Clamp	3.75
680-007	8' Power Cord	\$ 23.00
143-001	1/4" Hose Fitting	6.50
143-002	3/8" Hose Fitting	6.50
663-002	Rubber ISO Foot Mounts (4)	22.75
703-001	Rubber ISO Foot Mount Assembly w/ Plate	32.75
613-002	Bearing (1-33-RXP)	19.25
413-007	Inlet Screen 6" x 6"	5.50
413-008	Air Tank	35.75

*Recommended spare parts (Replace at least every 24 months) for continuous service.

*Includes USPS ground freight.



4310 North 126th Street Brookfield, WI 53005 U.S.A.
Phone: (262) 781-5020 Fax: (262) 781-8120